

Date Revised: 10/26/2009 Time: 900  
 Aircraft Number: N83LC Engine Models: TSIO520WB3F Continental

Model Baron 58P	Airframe S/N	TJ289	LH Engine S/N	274492-R
MFD: 02 JAN 1973			RH Engine S/N	274447-R

Inspection	Remaining	Due Time	Interval	Insp. Completed
First Inspection	39.80	1293.7	50	1243.7
Second Inspection	89.80	1343.7	100	1243.7
Third Inspection	47.10	1301	150	1151.0
Fourth Inspection	189.80	1443.7	200	1243.7
Fifth Inspection	147.10	1401	250	1151.0
Sixth Inspection	289.80	1543.7	300	1243.7

hobbs

Hobbs Time	1253.90
Airframe Total Time	7774.3
Engine Total Time LH	961.8
Engine Total Time RH	1479.5

Progressive Inspection Last Completed 10/30/2007

Wing Bolt Re-Torque	n/a
Heater Hobbs	1562.7 4-Sep-07

COMPONENT	PART	SERIAL	DATE PLACED	INSTALLED	CYCLE	RETIREMENT	OVERHAUL	Calendar time	REMOVE ON	OVERHAUL AT	TIME	TIME
DESCRIPTION	NUMBER	NUMBER	IN SERVICE	A/C HOURS	LIFE	LIFE	LIFE	Overhaul	Date	A/C HOURS	TO DATE	REMAINING
LH Engine #1	TSIO520WB3F	274492-R	29-Jun-00	5939.5			1600	N/A		7539.5	961.8	638.4
RH Engine #2	TSIO520WB3F	274447-R	30-May-99	6294.8			1600	N/A		7894.8	1479.5	120.5
LH Prop Governor			29-Jun-00	5939.5			1600	N/A		7539.5	961.8	638.4
RH prop Governor			30-May-99	6294.8			1600	N/A		7894.8	1479.5	120.5
Turbocharger #1			29-Jun-00	5939.5			1600			7539.5	961.8	638.4
Wastgate #1			29-Jun-00	5939.5			1600			7539.5	961.8	638.4
Turbocharger #2			30-May-99	6294.8			1600			7894.8	1479.5	120.5
Wastgate #2			30-May-99	6294.8			1600			7894.8	1479.5	120.5
Engine hoses #1	Kit		29-Jun-00	5939.5			1600	5yr.	8/xx/2005	7539.5	961.8	638.4
Engine hoses #2	Kit		30-May-99	6294.8			1600	5yr.	5/xx/2004	7894.8	1479.5	120.5
LG Actuator Assy.	95-810017-13						4000					
LH prop #1	PHC-J3YF-2UF	ED4385D	10/24/2006	7671.4			2000	or 6yr.	10/xx/2012	9671.4	102.9	1897.1
RH prop #2	PHC-J3YF-2UF	ED1762	10/24/2006	7671.4			2000	or 6yr.	10/xx/2012	9671.4	102.9	1897.1
Engine LH #1 Starter						O/C						
Engine RH #1 Starter	646275-1	H061578	08-Aug-08	7729.5		O/C					44.8	
Main Gear Assy.							2000					
Nose gear Assy.			11/xx/2001	7166.7			2000			9166.7		1392.4
LG Actuator Assy.	95-810017-9						2000					
LG Retract Motor	58-380090-1	4147	11/xx/2001	7166.7			2000			9166.7		1392.4
Shimmy Damper							2000					
Flap Motor & Drive							2000					
Flap Actuators							2000					
Oxygen Regulator							2000					



COMPONENT	PART	SERIAL	DATE PLACED	INSTALLED	CYCLE	RETIREMENT	OVERHAUL	Calender time	REMOVE ON	OVERHAUL AT	TIME	TIME
DESCRIPTION	NUMBER	NUMBER	IN SERVICE	A/C HOURS	LIFE	LIFE	LIFE	Overhaul	Date	A/C HOURS	TO DATE	REMAINING
Oxygen Tank Hydro.			12/6/2004					5yr.	12/xx/2009			